
Detailed Design and Engagement Update

> James Caspell Neighbourhood Director

28th January 2021

LANCASTER WEST NEIGHBOURHOOD TEAM

Detailed Design Overview







3.3 ENERGY ASSESSMENTS

From our initial investigations from site and previous reports provided by the client, it appears that Talbot Grove House and Morland House would benefit from extensive works to bring their energy efficiency to current/best practice standards. The existing buildings are leaky, cold, damp and the current windows are poorly maintained and are single glazed.

Talbot Grove House and Morland House have some existing EPC ratings as shown in the table below, which indicates that most EPCs are in Band D. As previously explained, EPCs cannot accurately describe a properties energy performance as they are based on SAP data.

	TALBOT GROVE HOUSE	MORLAND HOUSE
A	0	0
В	0	0
С	7 %	38%
D	73%	54%
E	20%	8%
F	0	0
G	0	0

Figure 50 - EPC DATA




Figure 51 - EcoDesign Passivhaus Options Report - Existing Heating Demand figure of 240kWh/m2/a shown

Over 50% of residents have reported a heating and hot water issue in the last 6 months

% of residents by block who have raised a repair, complaint or case by issue in the last 6 months



50 to 100+% of residents

20 to 50% of residents

Issue Type	Barandon Walk	Camborne Mews	Camelford Court	Camelford Walk	Clarendon Walk	Hurstway Walk	Morland House	Talbot Grove	Talbot Walk	Testerton Walk	Treadgold House	Verity Close
General Repairs	81.9%	80.6%	126.9%	84.7%	91.3%	89.3%	79.4%	66.7%	83.3%	61.0%	89.5%	97.2%
Heating / Hot Water	92.1 %	75.0%	61.5%	78.0%	72.1%	67.1%	73.5%	131.1%	50.0%	52.0%	55.3%	91.7%
Plumbing	82.7%	36. 1%	76.9 %	110.2%	113.5%	72.1%	50.0%	71.1%	66.7%	60.0%	89.5 %	80.6%
Leaks	49.6 %	19.4%	57.7%	64.4%	78.8%	52.9 %	55.9 %	80.0%	44.4%	56.0%	26.3%	58.3%
Intercom / Door Entry / Locks	64.6%	63.9%	11.5%	54.2%	25.0%	41.4%	29.4%	68.9 %	38.9%	58.0%	52.6%	83.3%
Electrical	41.7%	22.2%	46.2 %	55.9 %	31.7%	31.4%	26.5%	42.2%	72.2%	26.0%	55.3%	11.1%
Lighting	I 6.5 %	41.7%	34.6 %	32.2%	27.9%	I 8.6%	23.5%	46.7%	22.2%	20.0%	28.9 %	44.4%
Windows	5.5%	30.6%	7.7%	25.4%	7.7%	10.0%	20.6%	26.7%	0.0%	6.0%	23.7%	11.1%
Drains / Gullies / Guttering	8.7%	8.3%	7.7%	5.1%	9.6%	10.0%	2.9%	2.2%	5.6%	14.0%	0.0%	19.4%








PASSI-SASH

Passisash windows use superior tilt & turn mechanism and sustainably s softwood, hardwood or Accoya timber. These windows have been succ installed in certified Passivhaus / EnerPHit retrofit in London. The wind been approved for use in many conservation areas and are availa glazing bars and a wide range of bespoke options to closely match traditional window styles.









8 engagement workstreams

Jan 21 F	Feb 21 Mar 21	April 21	May 21	June 21	
Overall Progr	ramme				
The Walkway	s (Lot I)				
East Side (Lot	t 2)				
Morland Hous	se and Talbot Gr	ove Hous	e (Lot 3)		
Treadgold Ho	use (Lot 4)				
Camborne M	ews (Lot 5)				
Verity Close ((Lot 6)				
Notting Dale	Heat Network				

Workstream I: Overall Programme

- Involves areas that affect the whole estate and will need a consistent approach
- May include local projects/engagement, where learning could be estate wide

Key Objectives:

- I. Inform resident of scope and potential choices
- 2. Engage residents to help shape and deliver overall vision
- 3. Educate on sustainability measures and how relationship with homes may change
 - **Examples** The Sustainability Series
 - include: Light Follows Behaviour
 - Innovate UK (Treadgold)
 - Open House 2.0

