What if...

3. Kitchens to

maisonettes were

What if...

What if...

insulated to keep

flats warmer?

7. Studios had small 8. End walls were

4. The lift and stair


easier access?

we changed to allow


Typical Upper Plan - Maisonettes

Typical Lower Plan - Maisonettes

Your Homes





2. Small balconies were incorporated into internal space? made bigger?




What if...


What if... 5 Balconies to three 6. Stores became winter gardens?









gardens?










How Treadgold House looks now


Typical Floor Plan - Flats and Studios



How does your home work for you?



Examples of good design:




Improve small and dark balconies



Bigger kitchens and efficient storage



Semi-private garden areas for studios



Winter gardens to reduce cold spots



Better entrances to homes




6 Soft effective lighting

Your Buildings



Road layout 1963



Road layout today



Current garden and parking



What if...A new pedestrian entrance was added from the north and cars were moved away from homes?



What if...A new pedestrian gate was added on Bomore Road and ground floor flats had small gardens?



What if...Parking, gardens and a play area each had a defined space?



New external/bike stores



New windows



Refurbish original signage



Attractive, car-free gardens



Alternatives to concrete panels



4 Create a friendly welcome, addressing storage issues and improving the communal gardens



Summary of findings

Your concerns:

After various discussions with residents, the following concerns were made about your homes, your block and the wider Lancaster West Estate.

Ideas for possible works to address these issues are included to the right.

Photos of your buildings and homes



Compromised security and access with broken gates, inadequate lighting and limited overlooking.

The building and its entrances are hard to find.



Balconies are small and of limited use.


Regularly broken and noisy lift causing access issues for residents and general inconvenience.



Condensation and mould in homes caused by current thermal performance.



Roosting pigeons are limiting the use of balconies and causing mess on the building.



Underperforming external space. Issues with parking, storage and play.



Concerns
about the
general lack of
maintenance.

Home layouts do not reflect current patterns of living.

Ideas we discussed:

The following ideas were suggested by the consultant team or residents in response to issues raised by residents during the consultation events.

All these ideas require further investigation to examine feasibility and costs. They will be discussed with and reviewed by residents.

I refers to illustrations on the neighbouring Early ideas board.

Ideas

Your feedback

Reconfigured access and entrances for better safety.

There is strong support for this and it is a resident priority.

New lift and secure doors to improve circulation.

overwhelming support for this. This is a resident priority.

New insulation and ventilation strategy to improve the temperature and air quality in homes.

There is overwhelming support for this and residents are interested in exploring this further.

A more usable external space with new entrances, rationalised parking, improved storage lockers, bin storage and an improved garden and playspace.

There is overwhelming support for this. Play equipment to suit age of children in block should be explored.

New building perimeter with recognisable gates and signage.

There is strong support for this, there should be clear and recognisable signage.

A lighting strategy for the building and outside space.

There is strong support for this as safety is a priority.

Options for homes that maximise available space with a focus on kitchens and bathrooms and usable balcony or garden space.

There is strong support for this and early options have been discussed for each type of home.

Ensure that designs will stand the test of time, age well and consider future maintenance.

There is overwhelming support for this. This is a resident priority - the same mistakes should not happen again.

Immediate actions:

The following need to be taken forward as a priority:

- Audit and update the Fire Risk Assessmentfor all blocks, in both the short and long term.
- Implement an effective Repairs and Maintenance Strategy.
- Conduct a housing appraisal to establish whether people feel their homes respond to their current needs.
- > Check for and deal with asbestos.

Early projects:

Works across the estate

These are possible projects that apply to most homes, blocks and external spaces across the estate, and could start before the main refurbishment begins.

- Community safety improvements through; additional and better lighting, providing video door entry systems, and increased CCTV.
- Improve signage across the estate.
- Improvements to refuse areas, including providing space for recycling and disposal of larger items.
- Investigate interim home improvements in advance of full refurbishment, e.g mechanical ventilation, heating, plumbing and water pressure.
- Introduce a local lettings policy to meet local needs.
- Secure bike storage, and improved play spaces could be provided.
- Improvements to nursery facilities, and options for future location.

Suggested Pilot Schemes

Various localised works in vacant flats could be undertaken for technical investigations and to create show homes for residents to view.

Works to your block or home

These are possible projects specific to your home or block that could start before the main refurbishment work begins.

- Replacement of temporary front doors and repair broken kerbs by entrance.
- > Pigeon management and deterrents.
- > Potential temporary playground.
- Explore possibility of additional toilet in three bedroom maisonettes.

